


箇所図

135.674743,34.977189

135.677768,34.977189



135.674743,34.974090

1 / 1500

135.677768,34.974090

現況写真

別紙2



起点→終点写真



終点→起点写真

A photograph showing a riverbank with a tree trunk circled in red. The tree trunk is located in the center of the image, between two white vertical poles. The background shows green foliage and a river. The text "現況写真（拡大）" is at the top, and two red text boxes are at the bottom.

現況写真（拡大）

河川天端部から生えている支障木伐採

※起終点範囲内に計6本程度（全樹木の幹周は写真と同程度）